UNCLASSIFIED

AD NUMBER

AD519822

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors; Administrative/Operational Use; 17 NOV 1971. Other requests shall be referred to Office of the Adjutant General [Army], Washington, DC 20350.

AUTHORITY

30 Nov 1983, DoDD 5200.10; AGO ltr, 30 Jun 1984

UNCLASSIFIED

AD ____

TO: UNCLASSIFIED FROM: CONFIDENTIAL AUTHORITY:

AGC, 1, A/A, 30 Jun 16

UNCLASSIFIED

SECURITY MARKING

The classified or limited status of this report applies to each page, unless otherwise marked.

Separate page printouts MUST be marked accordingly.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSONAIS PROHIBITED BY LAW.

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U.S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

DEPARTMENT OF THE ARMY OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310(11 M REPLY REPER TO 23 March 1972 DAFD-OTT DAAG-PAP-A (M) (3 Mar 72) SUBJECT: Operational Reports Lessons Learned, 1st Avn Bde, 12th Cbt Avn (\mathcal{A}) Gp, 165th Avn Gp Theist Ending 31 Secolor 1991 S THIS DECLINES CHARLE A MAINTAIN A DISECTOR THE MET SHOW 00 PETERNY TO SERVICE SEE DISTRIBUTION 45 W A **PCRM** Section 2 of reports, subject as above, are forwarded for review and evaluation in accordance with para 4b, AR 525 15 The information contained in these reports is provided to insure that lessons learned during current operations are used to the benefit of future operations and may be adapted for use in developing training materiai. information of actions initiated as a result of your evaluation should be forwarded to the Assistant Chief of Staff for For. e Development, ATIN: DAFD OTT, within 90 days of receipt of this letter. 4. As Section 1 of subject reports are not pertinent to the Lessons Learned program, they have been omitted. BY ORDER OF THE SECRETARY OF THE ARMY: Colonel, Acting The Adjutant General DISTRIBUTION: Commanding Generals US Continental Army Command US Army Combat Developments Command US Army Materiel Command Commendants US Army Aviation School Regraded unclassified when se US Army Surveillance School US Army Signal School from classified inclosure. US Army Transportation School Operational rept. for period indica 31 let 71./ CONFIDENTIAL - 10 003 650

DISTRIBUTION (Cont'd) Copies furnished: Office, Chief of Staff, US Army (DWSA) Deputy Chiefs of Staff Chief of Research and Development Assistant Chiefs of Staff Chief of Engineers The Provost Marshal General OSD(SA) Assistant For Southeast Asia Forces Commanders in Chief US Army, Europe US Readiness Command Commanding Generals US Army, Alaska US Army Flight Training Center III Corps, ATTN: Director, Project MASSTER Commander, US Army Forces Southern Command Commandant of the Marine Corps Defense Documentation Center Commanding Officers US Army Land Warfare Laboratory

US Army Logistics Doctrine, Systems & Readiness Agency

US Army Mobility Equipment Research & Development Center

US Army Aviation Test Activity

Mesi process of the second

2

AVBAXS-C 17 November 1971
SUBJECT: Operational Report & ssons bearned (Headquarters, 165th Aviation Gre: Period Ending 31 October 1971, RCS CSFOR-65 (R')) (U)

- 2. (C) LESSONS LEARNED. COMMANDER'S CHURCHUATIONS, EMAIGATIONS, RECOMMENDATIONS AND COMMAND ACTION.
 - a. Personnel: None
 - b. Intelligence: None
 - c. Operations:
- (1) Observation: The TOKE of the 1650 CAG authorizes one Army Approach Control Facility; however, due in the transfer is aviation requirements in a combat environment, there are presently two functional "conventional type" approach controls.
- (2) Evaluation: At Hue/Phu Bai ar exp-riment was conducted to determine if the Army could operate a radar approach control utilizing the tactical GCA equipment, AN/TSQ-71A control van and the AN/TPN-18 ground approach control radar with IFF/Signature. The radar facility consisted of three TSQ-71A vans and TPN-18 radar sets with the controllers co-located. The radars were set up in the following configuration: one radar covered the airspace from ground level up to 3,000 feet and also the precision final approach course; the second radar covered from 3,000 feet to 6,000 feet and functioned as surveillance and vectoring radar; the third radar was set to cover from 6,000 feet to 9,000 feet with initial pickup, surveillance, and vectoring capabilities. The radar consoles were connected into the FSQ-75 consolewithin the approach control facility, a modification which proved to be unfeasible. The facility has now been changed to a conventional approach control with two radar sets for GCA approaches for the following reasons:
- (a) Elimination of the confusion inherent with the number of controllers required to operate such a complex within the limited space of the FSQ-75 console.
- (b) Under the experimental complex, this facility did not have a back-up system in the event of a radar failure, thus leaving an area uncovered under that concept.
- (c) The AN/TPN-18 is a tactical radar set and is not a dual channel system which is required for continuous 24 hour operation.
- (3) Recommendation: Present radar equipment within the army inventory is not adequate for the conduct of a RAPCON operation. A RAPCON requirement was identified for the support of army aviation operations. Subsequent combat operations will

DAFD-OTT 712137 Incl 1

CONFIDENTIAL

DOTHERASED AT 3 YEAR INVERVALS; DOCLARENTS AFTER 12 YEARS, DOD DIR STOLLED

AVBAXS-C
SUBJECT: Operational Report Leasure (Headquarkers, 165th Aviation Group)
Period Ending 3! October 1971, RCS CFFOR-65 (R3) (U)

require radar coverage to the remaining of all productions of suitable surveillance radars.

- (4) Command Action: The TrN is display a removed from the AN/FSQ-75. The FSQ-75 was returned to a conventional manual approach control, and the two radars were reconfigured to operational ground control approach.
 - d. Organization: None
 - e. Training:
 - (1) Language Barriers
- (a) Observation: During of introduction pilots all training was accomplished in French. This required Free in apeaking US instructor pilots to translate all material verbally into a common larguage.
- (b) Evaluation: The quality of braiding could be enhanced by the availability of compatible reference material.
- (c) Recommendations Foreign national state the receiving training conducted by US military instructors should have as a prerequisite a command of the English language.
 - (2) Training of Avionica Communication Equipment Repairment
- (a) Observation: School trained aviorities communication equipment repairmen were not familiar with the FSQ-75 and TPN-18.
 - (b) Evaluation:
- (1) When the US Army Signa: School at Ft Cordon discontinued the three week block of instruction on the FSQ-75 Avionics Communication Equipment Repairmen, gradultes were not familiar with the piece of equipment. Consequently, upon their arrival in RVN, they were not repable of performing maintenance on the group's primary control tower. The group recognical this lack of training by experiencing excessive outages of the FSQ-75. It was invented that a school must be established to provide the necessary training for the repairment (i). In May of 1971 the school was initiated. Instructors were two FAF terminal representatives under contract to the US Army. Classes were two Werk is length and averaged three to four students per class. The method of instruction when in "names or" usthod, therety giving the students a more practical knowledge of the mile shouling procedures and corrective action. The results of the course were immediately evident when the outage time decreased significantly.
- (2) It was discover a the general soft the MOS 26D course did not have a working knowledge of it. I.N in rade. A smooth was set up in conjunction with the FSQ-75 school to train radem repairments are somet twaited in the CONUS school were

AVBAXS-C
SUBJECT: Operational Report Lessons Leavest (Headquarters, 165th Aviation Group)
Period Ending 31 October 1971, NCS OSFOR-65 (R3) (U)

require radar coverage thereto represidente de aloptent/procurement of suitable surveillance radars.

- (4) Command Action: The TPN to displays and removed from the AN/FSQ-75. The FSQ-75 was returned to a conventional manual approach control, and the two radars were reconfigured to operational ground control approach.
 - d. Organization: None
 - e. Training:
 - (1) Language Barriers
- (a) Observation: During the training of Cambodian pilots all training was accomplished in French. This required Free in apeaking US instructor pilots to translate all material verbally into a common larguage.
- (b) Evaluation: The quality or training could be enhanced by the availability of compatible reference material.
- (c) Recommendations Foreign national attractor receiving training conducted by US military instructors should have as a prerequisite a command of the English language.
 - (2) Training of Avionica Communication Equipment Repairment
- (a) Observation: School mained avioring communication equipment repairmen were not familiar with the FSQ-75 and TPN-18.
 - (b) Evaluation:
- (1) When the US Army Signa: Solved at Ft Gordon discontinued the three week block of instruction on the FSQ-/5 Aviences Communication Equipment Repairmen, gradulates were not familiar with the piece of equipment. Consequently, upon their arrival in RVN, they were not rapable of performing maintenance on the group's primary control tower. The group recognized it is lack of training by experiencing excessive outages of the FSQ-75. It was invented that a school must be established to provide the necessary training for the repairmen (id.). In May of 1971 the school was initiated. Instructors were two FAR terminal representatives under contract to the US Army. Classes were two Werk is length and averaged three to four students per class. The method of instruction was in "bands or" usthod, therety giving the students a more practical knowledge of trouter shouling procedures and corrective action. The results of the course were immediately evident when the outage time decreased significantly.
- (2) It was discover a transfer and the MOS 26D course did not have a working knowledge of in I.N to rate . A result was set up in conjunction with the FSQ-75 school to train radam equations, remode at twaited in the CONUS school were

And the second second second second

AVBAIS-C § 17 November 1971 SUBJECT: Operational Report - Lossons Learned*(Headquarters, 105th Aviation Group)
Period Ending 31 October 1971, HCS CSFOR-65 (R3) (U)

not given sufficient instruction is the TPN is because of the acope of the instruction. When required to repair the TPN-18, the repairmen were limited,

- (c) Recommendation:
- (1) Emphasis on the "hands on" method of instruction has proven to be more effective than the "theory of circuityy" method used in the COMUS school. Recommend that COMARC analyse the POI for the 35L and 26D commens with a view toward integration of the "hands on" method of instruction.
- (2) Recommend that coordination through personnel channels to the major uning headquarters be effected to insure necessary 35120. 195 personnel for maintenance of avionics communication equipment are available on a timely basis.
- (d) Command Action: This headquarters continues to conduct the FSQ-75 and TPN-18 school.
 - f. Logistics: None
 - g. Communication:
 - (1) Repair and Maturn to User, Repair and Return to Stock (RRU/RRS) Systems
- (a) Observation: The turn around time for repair and return of mission ensemble sensor and aviance time is extremely excessive and nevernly affects the mission accomplishment of user units.
- (b) Evaluation: Besearch at this level has revealed that mission essential sensor and avionics components have been immed in for repair and not returned to the user within a reasonable time. In a 180 day region, 17 Doppler Antennas were turned in for repair, nine of these amounts were returned to the user unit for a 47% loss. In the same 180 day period, seven navigational computers were turned in for repair through the RRU/RRS program and nove of these items were returned for a loss of 10%. By projection of loss rate of mission essential equipment it can be determined that mission ready rate would drop to approximately 42% in a subsequent 180 day period if the RRU/RRS in the United States is not vastly improved. In addition it has been determined that the support received from the DS and GS support in country has been adequate. Nork orders are constantly reviewed to insure validity.
- (c) Recommendations: It is recommended that management procedures in CONUS be intensified with a view toward expeditions return of mission essential avionicand sensor components.
- (d) Command Action: Letters have been formanded to 1st Aviation Brigade and 34th General Support Group identifying this problem. This headquarters continually works closely with the support units in an abject to find a workship solution to this very significant problem.

3

AVBAXS-C 17 Hovember 1971 SUBJECT: Operational Report - Lessons Learned (Headquarters, 165th Aviation Group) Pariod Ending 31 October 1971, BCS CSFOR-65 (R3) (U)

(2) Processor Block Assemblies:

The state of the s

- (a) Observation: This unit experienced a shortage of processor block assemblies (FSN 5841-908-9022) due to overheating. Failure of the heater control transistors Q1 and Q2 caused the overheat condition.
- (b) Evaluation: Test flights established that processor blocks without heaters produced imagery comparable to that from blocks with operational heaters. Processor roller blockages due to flight delays were substantially reduced, and roller life was extended due to less frequent immersion in nitric acid solution required to clear blockages. Cockpit ambient temperatures were from 20°C to 30°C, with an average of 24°C. Temperature within the RO-166 was substantially above cockpit temperature.
- (c) Heater assemblies should be redesigned to provide climate stabilisation. The result would be longer equipment life and less maintenance down time due to heater failures.
 - (d) Command Action: This unit has disconnected the heater assemblies.
 - (3) Infrared Imagery: Unsatisfactory results with Anscopan film.
- (a) Observation: The Anscopan film, serial type 2913, FSN 6750-825-0270, does not produce satisfactory imagery when used in the sensor system of the OV-1 aircraft.
- (b) Evaluation: Tests were run comparing the Anscopan film and the Kodak film. The Anscopan film has very poor resolution and is almost impossible to interpret. The processing of a small strip of unexposed film showed the Kodak film to be clear and the Anscopan film to have derk areas across the film. The film test took place in September 1971 with film carrying June 1971 expiration. The Anscopan appears to be thicker as the emulsion rolls onto the drive mechanism of the casettes whereas Kodak film causes no such problem.
- (c) Recommendation: Until such time as the Auscopan film can be improved to acceptable standards, it should not be used in Vietnam.
- (d) Command Action: An urgent EIR has been submitted to the appropriate agency, and at present only Kodak film is being used.
 - (4) Increased Photo Capability:
- (a) Observations. The KA-76 camera has proven to be a high dependable and effective item of equipment.
- (b) Evaluation: The OV-iA model serves the dual role as visual/photo mission and training aircraft. The KA-30 camera system used exclusively in the OV-iA and OV-iC models are old and unreliable. This frequently results in multiple sorties

CONFIDENTIAL

AVBAIS-C
SUBJECT: Operational Report - Lessons Learned (Randonaters, 155th Aviation Group)
Period Rading 31 October 1971, RCS CSFOR-65 (R3) (U)

launched to complete a single mission. The EA-76 camera, previously designed exclusively for the CVI "Super C" is a newer and more reliable camera.

- (c) Recommendation: That an electrical cable should be constructed that allows the utilisation of the KA-76 casers system in the OV-1A. Using the modified cable and modified KA-30 casers sount the OV-1A has full vertical and obliques capability with increased mission reliability and fower masted flight hours.
- (d) Command Action: The 73d SAC has taken this action and is operating with greater camera reliability due to the sodification.
 - h. Material: Helicopter Skid Shoes
- (1) Observations Due to the high number of touchdown maneuvers associated with helicopter training activities, factory installed skid shoes last approximately 8 flight hours.
- (2) Evaluation: Experimentation with a locally fabricated skid shoe constructed of .090 inch cold rolled steel extended skid shoe life to 65 flight hours.
- (3) Recommendation: That heavy duty skid shoes of this general type be introduced in the supply system.
- (4) Command Action: This unit continues to have skid shoes reinforced with cold rolled steel at the DS level.

i. Other: None

LOWELL L BALLARD, JR.

LTC, IN Commanding AVEAGE (17 Nov 71) let Ind

SUBJECT: Operational Report - Leasons Learned for the 165th

Aviation Group (Combat), Period Ending 31 Not 71 (RGS: GSERRAGE
(R3) (U)

DA, Headquarters, 1st Aviation Brigade, Arn San Francisco ofash

TO: Commanding General, United States Army Vietnam, ATTY: AVENTARY APP San Francisco 96375

This Hecoquarters has reviewed the Operational Report - Leasons Isamed for the period ending 31 October and concurs.

FOR THE COMMUNICAR:

ur, and

Asst Adjutent Ceneral

AVHD0-D0 (17 Nov 71) 2nd Ind

JAN 1 3 1972

SUBJECT: Operational Report - Lessons Learned (Headquarters, 165th Aviation Group) Period Ending 31 October 1971, RCS CSFOR-65 (R3) (U)

Headquarters, United States Army Vietnam, APO San Francisco 96375

TO: Commander in Chief, United States Army Pacific. ATTN: GPOP-FD, APO 96558

This Headquarters has reviewed the Operational Report-Lessons Learned for the period ending 31 October 1971 from Headquarters, 165th Combat Aviation Group and concurs with comments of indorsing headquarters.

FOR THE COMMANDER:

CPT. AGC.

Assistant Adjutant General

GPOP-FD (17 Nov 71) 3d Ind (U)
SUBJECT: Operational Report-Lessons Learned, HQ 165th
Aviation Group, Period Ending 31 October 1971,
RCS CSFOR-65 (R3) (U)

HQ, US Army, Pacific, APO San Francisco 96558 9 FED 1972

TO: HQDA (DAFD-ZA) WASH DC 20310

This headquarters concurs in subject report as indorsed.

FOR THE COMMANDER IN CHIEF:

M. L. WAR 1LT, AGC Asst AG

AVIV US_O BIOJIICE:

12 Tovember 1971 Operational Report-Jessons Learned, 12th Combat Aviation Group for Period Unding 31 October 19,1, MGS CSFCR (N3)

- 2. (C) Lensons Learned: Commander's Observe juns, Evaluations and Recommendation:
 - a. Personnel: Note
 - b. Intelligence:
- (1) OUSIR will: Personnel and units release in their performance and mission execution by waking similar mistakes on a recurring basis.
- (2) ETALUATION: Lessons Learned, continuity files, unit SOP's are not being properly succeed. With the constant turbulence in personnel resulting from the 12 month RVM tour, costly losses in men and equipment are directly related to relearning the same axioms over and over again.
- (3) RECOURTEDATION: That a project be developed which summerizes Lessons Learned, to be issued to all units.
- (4) COMMIND ACTION: This headquarters is initiating action to provide subordinate units with the experience factor necessary to continually improve mission execution.
 - c. OTERATIONS:
 - (1) Operations from former? locations.
 - (a) COSCRVATION: factical headquarters that have operated from a fixed

DAFD-0TT 712086 Incl 2

CONFIDENTIAL

DOWNSRABID AT 3 YEAR INTERVALS; DECLASSING AFTER 12 YEARS. DOD BIR 5200.10

PROCEDERS THER BLANCHOF FIRMS

AVBAUS-C

12 Fovember 1971

SUBJECT: Operational Report-Lessons Learned, 12th Combat Aviation Group for Meriod Their 31 October 1971, RCS CSFCR (R3)

installation are not prepared to operate from a forward location.

- (b) TVALUATION: Large scale operations in remote area occur infrequently in MR3. As a result, bat alion and higher headquarters have become accustomed to operating from a fixed installation and are untile to rapidly establish a forward tactical operations center.
- (c) RECOMMEDATION: That each headquarters establish procedures for movement to forward locations and identify the personnel and equipment necessary to establish an operations center.
- (d) CONTAID ACTION: This headquarters is preparing an SOP for establishing a forward operations conver. Personnel and equipment necessary to operate the senter will be identified. Equipment not normally in use at the fixed location will be consolidated and stored. Equipment in normal use will be identified and tagged for mapid collection and movement.
 - (2) Security of Forward PoL/Rezim Points.
- (a) OBSERVATION: Forest POL/Means points are subject to theft/pilforage occurse aviation units cannot provide security.
- (b) EVALUATION: Aviation units do not have the capability to provide security for POL/Recem points at forward locations. As a result, the assumition, equipment and fuel is not recured after the operator departs the area.
- (c) RECCITEFOLTEO: That ARVN be encouraged to operate and provide recurity at forward FOL/Rearm points. Not only would this relieve the overburdened US aviation units, it would also give the ARVN valuable experience in operating and managing the points.
- (d) COMMAND ACITOR: This headquarters has requested and received ARVR assistance in securing former 100b, Rearm points. Also, this headquarters has submitted requests through TRAC encouraging ARVW to assume responsibility for oversting and maintaining former 10b/Rearm points in 1R3.
 - d. Organization: None
 - e. Training: Tone
 - f. Logistics:
 - (1) Flight Safety equipment.
 - (a) OBSERVATION: There is a shortage of flight safety equipment.
- (b) EVALUATION: The primary cause of the shortage of flight safety equipment is the individual aviator. Officers and Warrant Officers are not bringing their complete insue of flight safety equipment to RVN as authorised by AR 700-92. It is suspected that eviators are not being made aware of this

CONFIDENTIAL

AVM/US-C 12 Tovember 1971
SUBJECT: Operational Report-Ressons Rearned, 12th Combat Aviation Group
for Period Ending 31 October 1971, RCS CSECE (N3)

regulation by their preent commands prior to departure for RVW. It is also possible that some individuals are attempting to take advantage of the US Army by purposely leaving one issue at home and receiving a second issue in RVV. Additionally, unit supply personnel are not maintaining occurate accommobility of these items. Many individuals not on flight status are allowed to retain these items when they are not required or authorized.

- (c) RECOMMENDATION: That all aviators be required to have a full issue of flight equipment on hand prior to demating their last permanent duty station for RVH and that they be informed that they are required to take this with them to RVH. Aviators arrived in RVM without their issue (or proper documentation) would sign a statement of charges for a second issue. Unit convaders should also confiscate all flight equipment in the possession of Manuthorized persons and make the equipment available to authorized person of.
- (d) CONTENT ACTION: This headquarters conducted a survey of incoming personnel to determine reasons for sportages among new arrivals. Instructions have been issued to subordinate units to insure that only authorized personnel possess flight safety equipment.
 - (2) Unit Stand down Priority.
- (a) OBSTANTION: Some support units are standing down prior to the supported unit.
- (b) EVALUATIOF: Transporting equipment and supplies by vehicle is being complicated and above 1 down because transportation support units are standing down.
- (c) RECORDATION: That the stand down of supporting units be carefully coordinated with the stand down of supported units.
- (d) COMM ID ACTION: This headquarters has coordinated with remaining transportation units to attempt to obtain the required level of support.

g. Communications:

- (1) Observation: During the recent Tay Minh operation, difficulty was experienced in providing adequate communications for the forward element.
- (2) EVALUATION: The current INOE does not provide sufficient communications equipment to establish a formard operations center in addition to the normal communications requirement. This headquarters provides confunications for Group headquarters, two AAE's and a physical security defense net.
- (3) EXCOMMENDATION: That communications equipment be stockpiled for temporary lean to meet increased, temporary demand.
- (4) COMMAND AGRICON: This headquarters met the present situation by hand-receipting the equipment from other US units. This is a temporary solution

CONFIDENTIAL

AVBAUR-C

12 November 1971

SUBJECT: Operational Report-Lessons Bearned, 12th Combat Aviation Group for Perior anding 31 October 1971, RGS CSEVE (R3)

that will become less effective as more US waits atend down.

h. MATERIAL: Hone

i. PEDICAL: None

OHN HARRICIARY SOF

Colonel, In Cornarding

CONFIDENTIAL

AVBAGC (12 Nov 71) Ist Ind

SUBJECT: Operational Report - Lessons Learned, 12th Combat Aviation Group
For Period Ending 31 October 1971, RCS CSFOR-65 (R3) (U)

DA Headquarters, 1st Aviation Brigade, APO San Francisco 96384

TO: Commanding General, United States Army Vietnam, ATTN: AVHDO-DO, AFO San Francisco 96375

This Headquarters has reviewed the Operational Report - Lessons Learned for the pariod ending 31 October 1971 and concurs.

FOR THE COMMANDER!

The state of the s

1LT, AGC

Asst Adjutant General

JAN 1 3 1977

AVHDO-DO (12 Nov 71) 2nd Ind

Nov 71) 2nd Ind

SUBJECT: Operational Report - Lessons Learned, 12th Combat Aviation Group For Period Ending 31 October 1971, RCS CSFOR-65 (R3)

licadquarters, United States Army Vietnam, APO San Francisco 96375

TO: Commander in Chief, United States Army Pacific, ATTN: GPOP-FD, APO 96558

This Headquarters has reviewed the Operational Report-Lessons Learned for the period ending 31 October 1971 from Headquarters, 12th Combat Aviation Group and concurs with comments of indorsing bradquarters.

FOR THE COMMANDER:

CPT. AGC.

Assistant Adjutant General

GPOP-PD (12 Nov 71) 3d Ind (U)
SUBJECT: Operational Report-Lessons Learned, HQ 12th
Combat Aviation Group, Period Ending 31 October
1971, RCS CSFOR-65 (R3) (U)

HQ, US Army, Pacific, APO San Francisco 96558 9 FEB 1972

TO: HQDA (DAFD-ZA) WASH DC 20310

This headquarters concurs in subject report as indorsed.

FOR THE COMMANDER IN CHIEF:

7

a provide the forest of the transfer of the product of the product

M. L. MAR 1LT, AGC Asst AG N

AVBAGE
14 Sov 71
SUBJECT: Operational Export - Leasons Learned for Massiquerters, let Aviation
Bricade, Period Ending 31 October 1971, 868 CSPCR-63 (BJ) (D)

- 1. (C) Section II, Lessons Learned: Commander's Observation, Evaluation, and Resourcedations.
 - s. Personnal.
 - (1) Personnel status.
 - (a) Observations: There are no personnel strongth problems.
- (b) Evaluations: The let Aviation Erigade Fersonnel status has improved steadily throughout the period. The expensith has increased from a low of 90% authorised eviators to 96% of authorised. At the end of the reporting period there were no critical shorteges of any particular eviator skills. The overall experience level is low in the aviation units. Instructor Filoto in the AE-10 and LOE helicopters are the greatest need. These requirements have not bempered the Erigade mission.
 - (c) Recommendations: None.
 - (d) Commend Action: None.
 - (3) Prez Problèm.
- (a) Observations: The let Avietica Brigade experienced a drug prob-
- (b) Evaluation: The cajority of the identified drug abusers were younger personnel in the lower five pay grades. Echabilitation programs were enthusiastically condusted by the Erigade. 100 percent usinalysis detection programs were begun in the units commencing in September. The Erigade's rate of drug abusers identified through urinalysis was 4.8 percent as epposed to the USANV rate of 5.3 percent, indicating higher morale exemp eviction personnel.

DAFD-OTT 712091 Incl 3

CONFIDENTIAL

ESTREED IN 8 TEST ESTREES ESTREED IN 8 TEST EST

Confidential

AVEAUC 14 Nov 71 SUBJECT: Operational Report - Lesgons Learned for Meséquertors, 1st Aviation Brigade, Period Ending 31 October 1971, ECS CEPUR-63 (E3) (U)

- (c) Recommendations: Continued exphasis on rehabilitation and increased rates of elimination from the service for those who fail the programs.
 - (d) Command Action: Continued support of the approved programs.
 - (3) Morale.
- (a) Coservation: The morals of the 1st Aviation Brigade continues to be high.
- (b) Evaluation: The let Aviation Brigade continued to be tasked for combat missions during the period. The Brigade accomplished numerous combat actions resulting in enemy casualties. This factor enhanced the morale of the aviation units and contributed to a highly favorable rate for all morale indicators. In most categories, the Brigade's morale and welfare indicators wash more favorable than the UELER average. The Brigade's average rate per thousand personnel of crimes of violence and crimes against property was 1.09 as apposed to UELEV's 1.45; the Brigade's average rate of motor vahicle accidents per million miles was 3.8 compared to UELEV's 5.3; the Brigade emperioned an average rate per thousand of .7 deserters against UELEV's 0.65 percent. The above stated indicators show a slightly unfavorable trend over those for the last reporting period. The unfavorable increased are attributed to the increase of leigure time available due to the decrease in combat requirements.
- (c) Recommendations: Continued exphasis on intracural sports and related activities.
- (d) Command Action: Continued standdown of units whose combat mis
 - b. G-3 Operations: Mone.
 - c. Training: None.
 - d. Intelligence: Hone.
 - e. Logistics.

The same of the sa

- (1) Plight safety clothing and equipment.
- (a) Cocreation: lot Aviation Brigade units were not receiving timely support of required flight cafety eleching items.
 - (b) Evaluations.
- (1) Long Dinh Depot is the only location within EVH there flight safety election is stocked. Aviation units are located from the Delta to the EVE and were too for removed from the cupply source to adequately coordinate requirements with the Depot.
- (2) Elepso time from date of request to receipt of the item swerrege heaven (3-12) days. This necessitated a stockege of items at a point which would allow repid response to unit's needs.

ははいはいないとはいればいいいというないかられて

1

6 17

AVBAGO SUBJECT: Operational Report - Lessons Learned for Reciquarters, 1st Aviation Brissle, Period Ending 21 October 1971, RCS CSFOR-65 (R3) (U)

- (c) Recommendations: A request was made that the let Aviation Brigade G-4 Section to provided an account number allowing it to act as the Direct Support Unit (DSU) for all units.
- (d) Command estion: This request was approved and a storage and issue section was established at Sanford Army Airfield on 1 August 1971. This estion provided units ready access to flight elething as it was located on a major sirfield and maintained stock for immediate issue. A significant improvement in distribution of available assets was also realised as current transactions concerning flight safety items are required to be processed through the Brigade DSU.
- (2) Disposition of UE Government Property by inactivating/redeploying units.
- (a) Coccreation: Reports received at this headquarters indicated that inactivating/redsploying units were not properly disposing of all US Coverment property upon unit standdown.
- (b) Fraluction: A spot check of several units after standown determined that units were not ensuring that all equipment and supplies were properly returned to supply channels.
- (c) Recommendation: That subordinate units by advised of the policy to prografy "police" unit areas subscituant to unit standdown. It was also recommended that staff visits be confucted to each standdown unit to ensure its loverment property is returned to supply channels upon final close-cut of the unit.
- (d) Command Action: A command letter was dispatched to each Group on 14 October 1971 stating the policies concerning property accountability. In addition, a representative from the G-4 staff visits each insetivating/redsploying unit to ensure an adequate "except has been conducted and all El Covernment property has been disposed of IAW established turn-in procedures.
 - (3) Appeletment of Property Book Officers.
- (a) Checryation: Several units within the let Aviation Brigade were appointing junior grade efficers (Avn WO's, 217's, and 117's) as Property Lock Cricers.
- (b) Draketica: A rovice of Exports of Exvey, tharterly loss forcests and other papely accounting transactions rovaled that junior grade efficers because of their lack of curply training/experience word not mintuining unit property recents catholecturily. A rovice of the personnel states reports determined that there were enters officers in the grade of Cartain throughout the Ericals.

AV CACO

AV CACO

Personal Report - Lessens Loarned for Headquarters, 1st Aviation

Brigads, Period Ending 31 Cotober 1971, and Office-65 (10) (0)

- (c) Recommendation: That a policy he established on the established of the established on the established of
- (d) Command Action: A letter was dispatched to all subordinate units on 20 September 1971 commanding the appointment of Property Work Officers. The letter recommended that, where possible, unit Property Rock Officers of company size units would be unit Supply Technician Warrant Officers (761AD) or officers in the grade of Captain. The appointment of officers based upon experience/training with the US Army Supply System will greatly improve inventory accounting procedures and reporting at the unit level.

(b) UH-1 Fuel Switch Guard.

- (a) Observation: Investigation of a UH-1 accident in which angine failure was a contributing factor, revealed that a fuel switch guard was not installed.
- (b) Evaluation: Without the Switch guard installed it is easy to insdvertently switch the Suel ofr, particularly when performing hydroulice off landings.
- (c) Recreasedation: That immediate action be taken to install fuel switch guards on all UH-1 aircraft.
- (d) Command action: The Commanding General directed that, beginning 0600 hours 10 July 1971, all UH-1 aircraft not equipped with a fuel switch guard were grounded until such time as a guard was installed.
 - (5) UN-1, AM-1 Hydraulics Failures.
- (a) Observation: Analysis of prescutionary landings by UH-1 and AH-1 aircraft revealed that a predominant number were exceed by hydroulic failures.
- (b) Evaluation: 36% of the UE-1 and 46% of the AM-1 precautionaries in the first six menths of CY 71 were exaced by hydrculic failures with the majority exaced by chaffed lines. This was indicative of poor maintenance procedures and lask of comprehensive profilight inspections by flight crows.
- (c) Recommendation: That commenders, Maintenance Supervisors and Technical Inspectors encure that maintenance perconnel strictly ashere to proper maintenance precodures and that flight eroms perform thereugh and complete proflight improvious.
- (d) Commend Action: All units in the commend here been made aware of the hydroulic problem and the recommended colution.
 - f. Organization: Memo.
 - g. Information Office: None.

AVELOU Devational Report - Lacous Lacrati for Engineerics, 1st Evision Briggio, Period Heling II Orions 1971, NOS CROWLES (NS) (U)

- h. Signal: Fene.
- 1. Surgeon: ford.
- j. Safaty: Nasa.
- k. Chapisin:
 - (1) Pareness Elizables.
- (a) Chetrration: The Brigade had a total of twenty (20) chaplains at the regiming of the reporting paried. During the period ninetten (19) chaplains were lost and eleven (11) were gained, leaving a total of twelve (12) chaplains in the Erigade at the end of the reporting period.
- (b) Production: While there was elased a complete turn-over of chaplains and a major decrease in marker of essigned chaplains in the Brigade, no unit was without the services of a chaplain during the reporting period. Religious coverage for all three major faiths was countinated and supplied through adjacent unit chaplains and chaplains of the Brigade.
- (e) Recommunities: What additional chaptains to assigned to the Briggle so that religious coverage can be more edequately provided.
- (d) Command Action: WARY Staff Chaplain is owner of chaplain shortage. If and when additional obsplains are available, they will be accigned.
 - (2) Caligious and Gral Training.
- (a) Observations: Chiplains uses encouraged to premote the Charcoter fuldames program at their unit level and to mile une of the training aids available to them. In June a USANV Heligious Tetrast Center une Codicated by Compal Absent at Cas Bank Bay. Personnal uses authorized by rogulations, and five-day edministrative absence Curing their Victure term to attend one of their describational retreate. A morthly Drightle Chaplain's National terminal to know the Endoube chaplaine informat of circulational receives events. A mortal of the Chaplain Training Conference use initiated in September. All chaplains in the Drightle will in brought together, who a guarter for this training coorden.
- (b) Embedden to editional from estima occasi continued, the con tal core taken for religion editation on for cored on epirital training. Whis participation is still for from continued, the train is to distribute of providing a unfittible on effective religion program than the car of society compani.

AVBAGO STIJIUT:

14 Per 71 Operational Report - Reseas Learned for Escalquarters, 1st Aviation Erigodo, Porisd Rading 31 Ostober 1971, 808 08707-65 (RS) (V)

- (d) Command Actions Hose required,
- Esciquarters Commandant: None.
- Metorian: Cons.

dier Canaral, WA Comming

DISTRIBUTION

- 1 thru charmelo to ACSFOR (Orig Cy) 2 Direct ACSFOR DA (with lot Ind)

- 2 CIEDUSARRAC, ATTI: GPOF-DT 3 CG, USARV, ATTI: AVEDO-DO 1 O-3 F110

AVHDO-DO (14 Nov 71) 1st Ind SUBJECT: Operational Report - Lessons Learned for Headquarters, 1st Aviation Brigade, Period Ending 31 October 1971, RCS CSFOR-65 (R3) (U)

Headquarters, United States Army Vietnam, APO San Francisco 96375

TO: VCommander in Chief, United States Army Pacific, ATTN: GPOP-FD, APO 96558

HQ, DA (DAFD), Washington, D. C. 20310

This Headquarters has reviewed the Operational Report-Lessons Learned for the period ending 31 October 1971 from Headquarters, 1st Aviation Brigade and concurs.

FOR THE COMMANDER:

CPT. AGC.

Assistant Ljutant General

GPOP-FD (14 Nov 71) 2d Ind (U)
SUBJECT: Operational Report-Lessons Learned, HQ 1st
Aviation Brigade, Period Ending 31 October 1971,
RCS CSFOR-65 (R3) (U)

HQ, US Army, Pacific, APO San Francisco 96558 9 FEB 1972

TO: HQDA (DAPD-ZA) HASH DC 20310

This headquarters concurs in subject report as indorsed.

FOR THE COMMANDER IN CHIEF:

H. L. MAR ILT. AGC Asst AG

NOTE SOUTH THE

CRISING TIME ACTIVITY (CONCERN SORIO)

CONFIDENTIAL

	DECLMENT CONTROL DATA .		
	Deciment Continol Data - R	460	
(Security elassification of this, hole	of about and believing properties were be	and the second section of the	annell careet to elecablicat

COMPIDENTIAL

HQ, DAFD , DA, Washington, D. C. 20310

& snaup

Acres Vivie Operational Report - Lessons Learned for Headquarters, 1st Avn Bde, 165th Avn Gp, 12th Combat Avn Gp, for period ending 31 October 1971.(U)

4. DESCRIPTIVE MOTES (Type of regal and lectualty detail)

Experiences of unit engaged in counterinsurgency operations.

CG, 1st Avn Bde, CO, 165th Avn Gp, 12th Cbt Avn Gp

24 Pebruary 1972	76. TOTAL NO. OF PASSS 12. NO. OF REFS
62. CONTRACT OR GRANT NO.	en Grisinavor's report russers!
A. PROJECT NO.	712091 712137 712086
e	के. उपाद्यते विदेशियम् स्रम्था (देन्द्र क्टीन विकासकार तेना व्यक् ६० व्यवेद्वानी als regard)

II. BUPPLEMENTARY NOTES

O DISTRIBUTION STATEMENT

IS. SPORSERING MILITARY ACTIVITY

N/A

DAFD, DA, Washington, D. C. 20310

S. ASSTRACT

COMPENIAL

00 : 41473

unclassified

Security Constitution

